

IC18 SPREADER

RELEASE NOTES

USB updating is not available. Contact TeeJet Customer Service/Repair or OEM to get instructions for updating.

IC18 Spreader Language Addition v1.10

January 2018

New Feature:

- The following languages were made available:
 - DE German
 - · EN English
 - · ES Spanish
 - · PT Portuguese

IC18 Spreader v1.10

August 2016

New Features:

- · Official AEF certification as an ISOBUS ECU Control Function
 - · Conformance tested to:

UT generation 2.0

TC-BAS generation 1.0

TC-SC generation 1.0

Fixes:

Multiple changes to message structure and content to enhance ISO11783 compliance.

IC18 Spreader v1.08

July 2016

New Features:

- · Updated to Task Control Client Version 3
- Screens load and update faster
- · Cyrillic font support added for Rauch & Kuhn UT's.
- New setting to accommodate noise on the rate-sensor input when the applicator is not actually applying product

Fixes:

- Corrects problem where consecutive connections of the same implement may result in two object pools for the same implement being available on the terminal
- · Corrects problem on some terminals where touching the touch-screen results in a double-press response and unintended menu navigation
- · Corrects problem where buttons were not displayed properly on UT's with smaller data masks like the Fendt NT01-UT
- Corrects problem where the boom graphic is offset to the left or right of the tractor when IC18 is connected to some John Deere terminals
- · Corrects problem when changing between CAN Speed and Simulated Speed system restart no longer required
- Multiple changes to message structure and content to enhance ISO11783 compliance

NOTE: IC18 Spreader Release Notes before v1.08 release were not gathered in this format.

